

Evidencija o posetama radi održavanja

KONE nalog 000876134584

Broj ugovora 41890846

Naziv lokacije EMPIRET DOO BEOGRAD-NOVI BEOGRAD

SAP broj opreme 44011775

Serijski broj proizvođača 44011775

ID Opreme L1

Adresa TREŠNJINOG CVETA 11

Grad BEOGRAD

Poštanski broj 11090

Prisustvovao Milos DUBAK

Datum posete 5/5/2026 3:53:49 PM

Evidencija servisnih usluga	
Задаци на доњем прилазу	Modul status
Verification of entrance and corridor	✓
Verification of landing signalization	✓
Verification of landing door panels and landing door running	✓
Verification of landing door sill	✓
Verification of elevator car door sill	✓
Задаци за кров кабине лифта	Modul status
Verification of guide rail lubricator; if applicable	✓
Check elevator car roof stop switch(es) and inspection drive unit, if applicable	✓
Задаци на крову кабине лифта за врата на највишем прилазу	Modul status
Verification of landing door railing	✓
Verification of landing door lock	✓
Verification of landing door contact and lock contact	✓
Verification of closing weight or spring	✓
Verification of landing door bottom guides	✓
Verification of landing door closed gap	✓
Задаци на крову кабине лифта за све међуспратове	Modul status
Verification of landing door railing	✓
Verification of landing door lock	✓
Verification of landing door contact and lock contact	✓
Verification of closing weight or spring	✓

Verification of landing door bottom guides	✓
Verification of landing door closed gap	✓
Задаци у кабини лифта на прилазу	Modul status
Verification of door open button and car door running	✓
Verification of elevator car lighting	✓
Задаци на доњем прилазу за аутоматска врата	Modul status
Verification of landing door bottom guides	✓
Verification of landing door closed gap	✓
Задаци на спрату МАР-а	Modul status
Verification of residual current device	✓
Verification of the emergency function and the related emergency power supply	✓
Задаци у кабини са затвореним вратима	Modul status
Verification of signs	✓
Verification of elevator car interior	✓
Verification of car signalization; where installed	✓
Verification of elevator car door panels	✓
Verification of car door bottom guides	✓
Задаци на међуприлазима и на највишем прилазу	Modul status
Verification of landing door sill	✓
Verification of entrance and corridor	✓
Verification of landing signalization	✓
Verification of landing door panels and landing door running	✓
Задаци на доњем прилазу	Modul status
Провера јаме лифта	✓
Завршите посету одржавања	Modul status
Verification of filled maintenance logbook	✓
Verification of returning the unit to normal operation	✓

Ovo je evidencija o završetku gore pomenutih modula održavanja. Ukoliko postoje stavke na koje moramo da vam skrenemo pažnju, nakon ove posete član našeg tima će vam se javiti.

Komentari tehničara

Redovan servis lifta

Potpis Kupca



Ime kupca

876154584

Peđa Predojević