

Evidencija o posetama radi održavanja

KONE nalog 000876137888

Broj ugovora 41890846

Naziv lokacije EMPIRET DOO BEOGRAD-NOVI BEOGRAD

SAP broj opreme 44011776

Serijski broj proizvođača 44011776

ID Opreme L2

Adresa TREŠNJINOG CVETA 11

Grad BEOGRAD

Poštanski broj 11090

Prisustvovao Milos DUBAK

Datum posete 5/5/2026 3:53:50 PM

Evidencija servisnih usluga	
Задаци на доњем прилазу	Modul status
Verification of entrance and corridor	✓
Verification of landing signalization	✓
Verification of landing door panels and landing door running	✓
Verification of landing door sill	✓
Verification of elevator car door sill	✓
Задаци за кров кабине лифта	Modul status
Verification of emergency alarm battery	✓
Verification of electrical brake release device battery; if applicable	✓
Verification of upper guide shoes	✓
Verification of guide rail lubricator; if applicable	✓
Check elevator car roof stop switch(es) and inspection drive unit, if applicable	✓
Задаци у кабини лифта на прилазу	Modul status
Verification of door open button and car door running	✓
Verification of elevator car lighting	✓
Задаци у кабини лифта за најнижа врата прилаза	Modul status
Verification of landing door railing	✓
Verification of landing door lock	✓
Verification of landing door contact and lock contact	✓
Verification of closing weight or spring	✓

Задаци на спрату МАР-а	Modul status
Verification of residual current device	✓
Verification of emergency light in car	✓
Verification of the emergency function and the related emergency power supply	✓
Задаци у кабини са затвореним вратима	Modul status
Verification of signs	✓
Verification of elevator car interior	✓
Verification of car signalization; where installed	✓
Verification of elevator car door panels	✓
Verification of car door bottom guides	✓
Задаци на међуприлазима и на највишем прилазу	Modul status
Verification of landing door sill	✓
Verification of entrance and corridor	✓
Verification of landing signalization	✓
Verification of landing door panels and landing door running	✓
Задаци на доњем прилазу	Modul status
Провера јаме лифта	✓
Задаци у МАР-у	Modul status
Verification of emergency batteries for elevator control	✓
Verification of operation of brake release system	✓
Завршите посету одржавања	Modul status
Verification of filled maintenance logbook	✓
Verification of returning the unit to normal operation	✓

Ovo je evidencija o završetku gore pomenutih modula održavanja. Ukoliko postoje stavke na koje moramo da vam skrenemo pažnju, nakon ove posete član našeg tima će vam se javiti.

Komentari tehničara

Redovan servis lifta

Potpis Kupca



Ime kupca

876137868

Peđa Predojević

"Ovaj imejl se automatski kreira OBAVEŠTENJE: Informacije koje su sadržane u ovom imejlu i svi prilozi su strogo privatni i poverljivi i mogu imati zakonske privilegije. Ukoliko vi niste primalac koji je trebalo da dobije imejl, molimo kontaktirajte pošiljaoca povratnim imejлом. U ovom slučaju ne treba da koristite, razlašavate, distribuirate, reprodukujete, skladištite ili postupate u skladu sa ovim mejlom ili bilo kojim priložima, treba da uništite ovaj imejl i sve priloge ili kopije. Preduzeli smo mere predostrožnosti da umanjimo rizik od prenošenja softverskih virusa, ali vam savetujemo da sami izvršite proveru virusa na ovom imejlu i svim priložima koje sadrži. Ne možemo prihvatiti odgovornost za bilo koji gubitak ili štetu izazvanu softverskim virusima. Kone d.o.o., Omladinskih Brigada 90 D, sprat 6, 11070 Beograd-Novi Beograd, telefon: +381 11 3591 230, email: ksb.info@KONE.com"